	Release Findings	
Mine Name: Ursa Major	fay 13, 2014	
Operator: Land of Health	I.D. No.: S.055/0017	
Operator. Land of Health	Mineral Ownership:	
	Surface Ownership: _	BLM
Disturbed and Bonded Area: 1 Acre		
Acres Requested for Full Release: Acres to be Release with this Action: 1 Acre		
		1.111 1 1
Comments: (if no acreage to be released, but only	monies, describe wny? (i.e.	arili nole plugging only)
Surety		
(1)	P	Cook
Total Surety Amount: \$3,000.00 plus interest	Form:	Casn
Amount Requested for Release: \$3,000.00	plus interest	-
Amount Recommended for Released: \$3,000.00	plus interest	_
NOTE: (Discuss each section as appropriate for the site – delete non-appropriate sections) Delete current text that is Italic).		
Operations		
The Operator removed small amounts of humate.		
Reclamation		
General: Operator reclaimed the site. See BLM email and letter		
<u>Public Safety</u> : Describe how the operator has reclaim minimized, reduced or eliminated. The description is safety and welfare hazards have been minimized, red safely removed or neutralized?	hould include how the Divis	ion has determined that all public
No public safety issues are present on site.		
Facility issues are present on site.		
Slopes, Highwalls, and Pits: Are all slopes and high	mwalls graded to a stable cor	oficination Are highwalls sland
to a 45 degree angle or less?	iwans graded to a stable con	giguranon. Are nignwans stopea
No highwalls or pits are left on site.		

<u>Plugging of Drill Holes and Closing Adits, Shafts, Etc.</u>: Describe number of holes and how they were plugged. Describe how shafts, adits, etc. were closed.

<u>Dams, Impoundments, and Drainages</u>: Are all water retaining features regraded, self draining, or of some postmining value? Describe the reclamation of these features and if not reclaimed how these feature meet public safety and the postmining land use. Are drainage channels re-established, stable and able to carry the anticipated flows.

NA

<u>Roads</u>: Have all roads been reclaimed (except pre-existing roads)? If not, describe the continued use and reference letter from land management agency/land owner requesting road to be left. Do the remaining road have adequate surface drainage structures for the continued use?

All roads have been reclaimed

Revegetation. Describe the revegetation work completed and date of last seeding. For full release, describe how the success standard 70 percent of the premining vegetative ground cover was determined. List species established and how they will meet the postmining land use. Has the vegetation lasted 3 growing seasons? Are noxious weeds being controlled?

The area and surrounding area has no vegetation.

Recommendation

Provide a recommendation for release of all or part of the bond amount.

Site should receive full bond release.

Permit Lead